




MOLD MAKING




1. The desired shape is CNC'd out of foam



2. This shape is then placed into plywood to prepare for the mold



3. Plaster is poured into the plywood around the foam



4. After the plaster hardens, the foam is removed to reveal the finished mold